

Main Wire Harness Replacement

TENNANT

Model: 5680

NOTICE: This instruction bulletin applies to 5680 models manufactured before serial 10551746 (Dec 2011). The new replacement harness is equipped with a 7.5 amp fuse to protect the scrub head lift actuator circuit. The installation of the new harness remains the same as the previous harness with the exception of the following wire connection as shown below.

