
KIT NO. 1068356



Brush Motor Replacement Kit

NOTICE: Brush Motor (p/n 222255) has been discontinued and replaced by this motor kit. Install replacement motor kit as illustrated below at right.

5700/XP/XPS - 800HD, 900D Disk Models



Motor Replacement Kit (p/n 1068356) **IMPORTANT:** For proper motor alignment, position motors as shown below. For early scrub decks, the motor mount hole pattern may not accept replacement motor. A new scrub deck will be required. Contact Service. 1063463 (Amer Motor) 3 Adapter Plate & Spacer Ring not required

TENNANT

Kit Contents

REF	PART #	DESCRIPTION	QTY.
1	1063463	MOTOR, ELE 36VDC 300RPM 1.0HP	1
	1066573	CARBON BRUSH REPLACEMENT KIT, (Set of 4) For Motor 1063463 - Not included w/ kit.	1
2	1068342	HARNESS, ADAPTER, MOTOR	1
3	00928	KEY, SQ, 0.25X0.25, 1.00L	1
4	09291	SCREW, HEX, M10X1.50X20,SS	4
5	41187	WASHER, FLAT, BELLEVILLE, .38	4

Please keep this sheet with your owner's manual for future reference.