



BrainOS Release 2.13.2

Highlights

This document summarizes the key product enhancements and updates available in the Brain Corporation BrainOS 2.13.2 navigation software release.

New software releases download automatically to your machine(s), much like they would for your mobile device. After it downloads the software update completely, your machine will be able to take advantage of the updates listed in this document on the next machine power cycle.

While this document highlights the key changes in BrainOS release 2.13.2, the release contains additional back-end enhancements. For a more in-depth explanation of the product enhancements that you will now be able to take advantage of, or if you simply have questions about this release, we encourage you to contact your authorized account representative.

©2020 Brain Corporation. All rights reserved.

BrainOS Release 2.13.2

This document lists the new features, improvements, bug fixes, and known issues for the Brain Corporation BrainOS version 2.13.2 software release. After it downloads to your machine, this version will automatically be available after the next power cycle.



Improvements

Updated the “Loading” animation displayed on the screen when the BrainOS software is first starting up.

Bug Fixes:

Pressing the Start/Pause button when a machine is on route repeat (formerly looping) stops the machine as intended. The machine does not move until the Start/Pause button is pressed again.

Changed the resolution steps for error 20001 (Route Error) from:

1. Turn off machine.
2. Wait 15 seconds.
3. Turn on the machine.

Contact supervisor if problem continues.

To:

Retrain the route, starting and ending at the same Home Marker.