TENNANT® COMPANY

Tennant AMR Software 3.5 Update


3.5 Release Highlights

- New Preferences Menu in Settings
- Area Fill Improvements
- Mobile Alerts UX
- Performance Improvements



New Preferences Menu in Settings

Local Enablement of Optional Features




Note: Area Fill should not be enabled in retail spaces or other environments with narrow or congested spaces



Area Fill Improvements

Automated Segmentation of Complex Spaces



Single Ranking Direction

Heavy Overlap


Excessive U-turns

- neavy Ovenap
- Constrained to Ideal Environments
- 5 Unique Sections
- "Bit by Bit" vs. "All at Once"
- Increased Efficiency, Reduced Overlap
- Suits the Real World



Mobile Alerts UX

An Additional Access Point for Connecting to Mobile Alerts





Performance Improvements

- Reduction in getting stuck when navigating near or around false assists caused by dark/shiny obstacles.
- Reduced shaking & jerking from the steering wheel during autonomous operation

