

Brush Motor Replacement Kit




Models: T5, T5e, and Speed Scrub 24-32 Cylindrical Brush

This motor replacement kit is intended for machines manufactured before serial number 10419662. Brush motor p/n 604980 has been discontinued and replaced by this kit which includes additional parts for proper installation. Carefully follow the installation instructions below.

INSTALLATION INSTRUCTIONS:

A WARNING: Electrical Hazard. Disconnect Battery Cables Before Servicing Machine.



* For carbon brush replacement kit, order p/n 1049739 (Kit includes 4 brushes)

Harness, Adapter, Motor (Kit 1050370)

1053363

4

1

Trim Plastic