




# Brush Motor Replacement Kit



**NOTICE:** Brush Motor (p/n 377440) has been discontinued and replaced by this motor kit. Install replacement motor kit as illustrated below at right.

## 5700/XP/XPS 700D, 800D Disk Models



### Kit Contents

REF	PART #	DESCRIPTION	QTY.
1	1063226	MOTOR, ELE 36VDC 320RPM 0.50HP, 15.0A	1
	1066573	CARBON BRUSH REPLACEMENT KIT, (Set of 4) For Motor 1063226 - Not included w/ kit.	1
2	00928	KEY, SQ, 0.25X0.25, 1.00L	1
3	1069606	GASKET, END BELL	1
4	1066734	HARNESS, ADAPTER, MOTOR	1
5	09007	SCREW, HEX, M6X1.00X25	4
6	41186	WASHER, FLAT, BELLEVILLE, .31	4

Please keep this sheet with your owner's manual for future reference.